


For Technical Support visit us at ownerscorner.sunsetter.com or Call Toll Free 800-670-7071 • Fax 877-224-4944



Tube #3 Bottom Cap Replacement Instructions

Tools Needed: Phillips Screwdriver

Parts Supplied: Bottom Cap (FP015-1), Mounting Screws (qty 2)

<u>WARNING</u>: THE METAL PARTS COULD HAVE SHARP EDGES. TO PREVENT THE RISK OF INJURY, USE SAFETY GLOVES WHEN REMOVING OR REPLACING PARTS. FAILURE TO DO SO COULD CAUSE PERSONAL INJURY.

WARNING: FAILURE TO FOLLOW THESE INSTRUCTIONS CAN RESULT IN PERSONAL INJURY! PLEASE READ THESE INSTRUCTIONS COMPLETELY BEFORE PERFORMING THIS PROCEDURE.

- 1. Remove the top three sections of the pole by holding in the bottom Spring Button while extending the section upwards and sliding the top three sections completely out of tube #4.
- 2. Remove the Bottom Cap mounting screws and remove the Bottom Cap.
- 3. Align the slot in the Bottom Cap with the track inside the tube and slide the new Bottom Cap into the tube.
- 4. Install the two new Bottom Cap mounting screws.
- 5. Place the top three sections of the pole back into tube #4. Lower them slowly until the Spring Button pops out of the hole in tube #4. Be sure to line up the slot in the Bottom Cap with the track on the inside of the tube.
- 6. Test the Flagpole for proper operation.