


For Technical Support visit us at ownerscorner.sunsetter.com or Call Toll Free 800-670-7071 • Fax 877-224-4944



Tube #3 Clear Bushing Replacement Instructions

Tools Needed: Phillips Screwdriver

Parts Supplied: Clear Bushing (FP021-1)

<u>WARNING</u>: THE METAL PARTS COULD HAVE SHARP EDGES. TO PREVENT THE RISK OF INJURY, USE SAFETY GLOVES WHEN REMOVING OR REPLACING PARTS. FAILURE TO DO SO COULD CAUSE PERSONAL INJURY.

<u>WARNING</u>: FAILURE TO FOLLOW THESE INSTRUCTIONS CAN RESULT IN PERSONAL INJURY! PLEASE READ THESE INSTRUCTIONS COMPLETELY BEFORE PERFORMING THIS PROCEDURE.

- 1. Remove the top two sections of the pole by holding in the middle Spring Button and extending the sections upwards and out of pole #3.
- 2. Remove the tube #3 Clear Bushing by depressing the two clear tabs while pulling the Clear Bushing up and out of the pole section. Note the alignment of the old Clear Bushing.
- 3. Align and insert the new Clear Bushing into the tube section.
- 4. Place the top two tube sections back into the main tube assembly. Lower them slowly until the Spring Button pops out of the hole in tube #3. Be sure to line up the slot in the Bottom Cap with the track on the inside of the tube.
- 5. Test the Flagpole for proper operation.